



Bell ATM Service, Inc.

8100 S. Akron Street, Suite 308
Centennial, CO 80112

888.772.1990 Toll Free
303.740.8370 Phone
303.740.8162 Fax
Sales@BellATM.com

Bell ATM Service, Inc. Flat Rate Repairs

Bell ATM Part Numbers

Standard prices only: See notes below

Test	Standard test fee on any unit or component	\$50.00
------	--	---------

Board Repair

Nautilus Hyosung		
BrdRep:NHGENMB	Repair of Tranax/Hyosung Main Board (Flash only)	\$65.00
BrdRep:NHGENMBARM9	Repair of Tranax/Hyosung ARM9 Main Board (Flash only)	\$65.00
BrdRep:NHGENMB-SRAM	Repair of Tranax/Hyosung Main Board w/SRAM failure	\$109.00
BrdRep:NHNANOMBC	Repair of Tranax/Hyosung Nano Main Board	\$129.00

Tidel		
BrdRep:TD1000MB	Repair of Tidel IS-1000 Main Board	\$149.00
BrdRep:TD2000FUJIDISPBRD	Repair of Fujitsu Dispenser Main Board	\$229.00
BrdRep:TD2000MB	Repair of Tidel IS-2000 Main Board	\$149.00
BrdRep:TD2000MODBRD	Repair of Tidel IS-2000 Modem Board	\$80.00
BrdRep:TDGENMB	Repair of Tidel IS-3000 Main Board	\$249.00
BrdRep:TDMULTIPRTRBRD	Repair of Tidel IS Series Printer Board	\$79.00

Triton		
BrdRep:TRGENDISP1700BRD	Repair of De La Rue SDD 1700 Dispenser Main Board	
	* With Dispenser	\$100.00
	* Without Dispenser	\$135.00
BrdRep:DNCMC	Repair of De La Rue NMD CMC Board	\$229.00
BrdRep:DNNFC	Repair of De La Rue NFC Board	\$229.00
BrdRep:TR9100DISPTDMBRD	Repair of Triton TDM Dispenser board	\$100.00
BrdRep:TR9100DISPTDMBRD-TW	Repair of Triton TDM Dispenser board with timing wheel	\$150.00
BrdRep:TR9100MB	Repair of Triton 9100 Main Board (Color or Mono)	\$120.00
BrdRep:TR9600CPU	Repair of SS1 CPU Board - Triton 9600	\$89.00
BrdRep:TR9600EXPBRD	Repair of SS4-5 Expansion Board - Triton 9600	\$89.00
BrdRep:TR9600KPADDOCKBRDV	Repair of Triton 9600 Visa docking board	\$50.00
BrdRep:TR9600MEMMB	Repair of SS2 Memory Board - Triton 9600	\$119.00
BrdRep:TR9600MODMB	Repair of SS3 Modem/Display Board - Triton 9600 w/no modem	\$129.00
BrdRep:TR9600MODMB-WM	Repair of SS3 Modem/Display Board - Triton 9600 w/modem needed	\$162.00
BrdRep:TR9600PRTRBRD	Repair of Triton 9600 Printer Control Board	\$189.00
BrdRep:TR9700MB	Repair of Triton 9700 Main board	\$149.00
BrdRep:TRGENDISPMMBRD	Repair of De La Rue Mini-Mech Dispenser Main Board	\$129.00
BrdRep:TRGENDOCKBRD	Repair of Triton RL/FT 5000 Docking Board	\$129.00
BrdRep:TRGENMB	Repair of Triton RL-5000 Main Board	\$295.00
BrdRep:TRGENMB	Repair of Triton RL-5000 Main Board w/component level repair	\$395.00
BrdRep:TRGENPRTRBRD	Repair of Triton RL/FT Printer Control Board & 9100	\$79.00
BrdRep:TRMAKODISPMB	Repair of Triton Mako Uni-Note Dispenser Main Board (Color or Mono)	\$120.00
BrdRep:TRMAKOMB	Repair of Triton Mako Main Board (Color or Mono)	\$120.00
BrdRep:TRMULTIMOD	Repair of RT2000/5000 Modem	\$80.00

Tranax		
BrdRep:TX1700MB	Repair of Tranax 1700 Main Board	\$149.00
BrdRep:TXC4000MB	Repair of Tranax MB (10.4" Color LCD)	\$79.00
BrdRep:TXDISPBRD	Repair of Tranax dispenser board	\$150.00
BrdRep:TXDISPMCDUBRD	Upgrade of Tranax dispenser mainboard from small pully to large pully	\$100.00
BrdRep:TXPRTRBRD	Repair of Tranax printer board	\$129.00

Cassette Repair

Nautilus Hyosung			
CassRep:NHGENCASS	Repair of Tranax/Hyosung Cassette	\$75.00	
CassRep:NHGENCASS-NSEP	Repair of Tranax/Hyosung Cassette w/note separator assembly	\$317.00	
CassRep:NHGENCASS-NSEP-PARTS	Repair of Tranax/Hyosung Cassette w/note separator parts only	\$239.58	

Tidel			
CassRep:TD2000CASSFUJI	Repair of Tidel Fujitsu Cassette	\$139.00	
CassRep:TD3000CASSMCDMII	Repair of Tidel MCDM II Cassette	\$150.00	
CassRep:TD3000CASSMCDMIII	Repair of Tidel MCDM III Cassette	\$150.00	

Triton			
CassRep:TRGENCASS1700	Repair of De La Rue SDD 1700 Cassette	\$142.00	
CassRep:TRGENCASS1700MFD	Modification of De La Rue SDD 1700 Cassette	\$106.00	
CassRep:TRGENCASSMM	Repair of De La Rue Mini-Mech Cassette	\$45.00	
CassRep:TRMULTICASSNMD100	Repair of De La Rue NMD 100 Cassette	\$175.00	Does not come with Reject Cassette
CassRep:TRMULTICASSNMD100R	Repair of De La Rue NMD 100 Reject Cassette	\$180.00	
CassRep:TRMULTICASSNMD50	Repair of De La Rue NMD 50 Cassette	\$175.00	
CassRep:TRMULTICASSNMD50RLCK	Repair of De La Rue NMD Cassette Reject (Locking)	\$130.00	
CassRep:TRMULTICASSTDM	Repair of Triton TDM Cassette	\$50.00	

Tranax			
CassRep:TXMULTICASSMCDU	Repair of Tranax MCDU Cassette (T or B)	\$150.00	

Dispenser Repair

Nautilus Hyosung			
DispRep:NHGENDISP	Repair of Tranax/Hyosung Dispenser	\$249.00	Excludes Drawer style Disp. Requiring note separator.
DispRep:NHMULTIDISP4K	Repair of Tranax/Hyosung Dispenser 4K	\$349.00	

Tidel			
DispRep:TD2000DISPFUJI	Repair of Tidel Fujitsu Dispenser	\$199.00	
DispRep:TD3000DISPMCDMII	Repair of Tidel MCDM II Dispenser	\$225.00	
DispRep:TD3000DISPMCDMIII	Repair of Tidel MCDM III Dispenser	\$225.00	

Triton			
DispRep:TR8100DISPTDM50	Repair of Triton TDM-50 Dispenser	\$229.00	
DispRep:TR9100DISPTDM100	Repair of Triton TDM 100 Dispenser	\$229.00	
DispRep:TRGENDISP1700	Repair of De La Rue SDD 1700 Dispenser	\$250.00	
DispRep:TRGENDISP1700RL	Repair of De La Rue SDD 1700 Rear Load Dispenser	\$325.00	
DispRep:TRGENDISPMM	Repair of De La Rue Mini-Mech Dispenser	\$189.00	
DispRep:TRGENDISPTDMEX	Repair of Extension for a Triton TDM 250 Dispenser	\$100.00	
DispRep:TRMAKODISP	Repair of De La Rue Uninote/Mako Dispenser	\$325.00	
DispRep:TRMULTIDISPNDM100	Repair of De La Rue NMD-100 Dispenser	\$449.00	Excludes damaged plastic side panels or extensions
DispRep:TRMULTIDISPNDM50	Repair of De La Rue NMD-50 Dispenser	\$349.00	Excludes damaged plastic side panels or extensions
DispRep:TRMULTIDISPTDM150	Repair of Triton TDM-150 Dispenser	\$249.00	
DispRep:TRMULTIDISPTDM200	Repair of Triton TDM-200 Dispenser	\$349.00	
DispRep:TRMULTIDISPTDM250	Repair of Triton TDM-250- Dispenser	\$349.00	

Tranax			
DispRep:TXGENDISP	Repair of Tranax Dispenser	\$249.00	
DispRep:TXMULTIDISPMCDU	Repair of Tranax MCDU Dispenser	\$375.00	Upgrade included.

Keypad Repair

KPADRep:GENKPADV	Reset Only - Keypad, Alpha-Numeric (Triton, Tranax, Hyosung)	\$65.00	
KPADRep:GENKPADVEPPI	Repair of EPPI Keypad (Tidel,Tranax,Hyosung)	\$205.00	

Triton			
KPADRep:TRGENSPED	Repair of Keypad, Alpha-Numeric, SPED,Triton	\$50.00	

LCD/Screen Repair

Nautilus Hyosung			
LCDRep:NH5000LCD	Repair of 10.4" Hyosung 5000CE LCD	\$109.00	

Triton			
LCDRep:TRMULTILCD	Repair of Triton RT2000/RL5000 LCD	\$180.00	

Tranax			
LCDRep:TXC4000LDCD	Repair of Tranax C4000 LCD	\$109.00	

Printer/Presenter/Modem Repair

Nautilus Hyosung			
PRTRRep:NHMULTIPRTRASSY	Repair of Tranax/Hyosung Printer Station	\$129.00	PCB Board Not Included

Tidel			
PRTRRep:TDGENPRTR	Repair of Tidel Thermal Printer	\$189.00	

Triton			
PRTRRep:TR9600PRTR	Repair of Triton 9600 Printer	\$189.00	PCB Board Not Included
PRTRRep:TR9700PRTR	Repair of Triton 9700 Printer	\$175.00	PCB Board Not Included
PRTRRep:TRGENPRTR	Repair of Triton Printer	\$99.00	PCB Board Not Included
PRTRRep:TRRL5000PRTRPRES	Repair of Triton RL Presenter	\$65.00	PCB Board Not Included
PRTRRep:TRRL5000PRTRTOTASSY	Repair of Triton RL Printer Assembly	\$129.00	PCB Board Not Included

Power Supply Repair

Nautilus Hyosung			
PSRep:NHGENPS	Repair of Tranax/Hyosung MB Power Supply	\$169.00	
PSRep:NHNANOPS	Repair of Tranax/Hyosung Nano Machine Power Supply	\$149.00	

Triton			
PSRep:DNPS	Repair of Triton NMD 100 Power Suppl	\$149.00	
PSRep:TR9100PS	Repair of Triton 9100 Machine Power Suppl	\$149.00	
PSRep:TRGENPS	Repair of Triton 9600/Tidel Machine Power Suppl	\$149.00	
PSRep:TRMULTIPS	Repair of Triton Power Supply	\$149.00	
PSRep:TRRL5000PS	Repair of Triton RL5000 Machine Power Suppl	\$169.00	

Tranax			
PSRep:TXGENPS	Repair of Tranax Power Supply	\$169.00	

Flat Rates Do Not Include the Following:

PCB Main Board repair or replacement
 Physical or shipping damage to any component or part of the machine
 Replacement of missing parts
 EPROM resets

ALL TRADEMARKS BELONG TO THEIR RESPECTIVE OWNER - PRICES SUBJECT TO CHANGE WITHOUT PRIOR NOTICE