

Hyosung ATM Upgrade Matrix

ATM Model	Keypad Version	ATM Core	Replace ATM?	Replace Keypad?	Software Version Required
MBxxxx					
NH1500		Firmware	Yes		
NH1800					
NH2100T					
NH1800		Firmware	Yes		
NH2100T		Firmware	Yes		
NH1800CE		WinCE 5.0	Yes		
NH5000CE					
NH5300CE					
MX5000XP		852, 945, G41	Yes		
MX5100					
MX5100T*					
MX5300XP*					
MX5600					
MX5600T					
MX7000D					
NH1500SE	EPP-6000K (or older)	WinCE 6.0	No	Yes - EPP-X1	MoniPlusCE2 - V06.03.00
NH1800SE					
NH2600SE					
MX2600SE					
NH2700					
NH2700T					
MX4000W					
MX5000SE					
MX5200SE					
MX5300SE					
MX5100T	EPP-6000K (or older)	H81, Q87, Q170	No	Yes - EPP-X1	MP2S Retail - v1.2.0
MX5300XP					
MX5300A/S					
MX5600					
MX5600T					
NH1500SE	EPP-8000R EPP-X1	WinCE 6.0	No	No	MoniPlusCE2 - V06.03.00
NH1800SE					
NH2600SE					
MX2600SE					
NH2700					
NH2700T					
MX2800SE					
MX2800T					
MX4000W					
MX5000SE					
MX5200SE					
MX5300SE	EPP-X1	WinCE 7.0	No	No	MoniPlusCE2 - V06.03.00
MX2600SE					
MX2800SE					
MX2800T					
MX5200SE					
MX5400SE	EPP-8000R EPP-X1	SBC210, H81, Q87, Q170	No	No	MP2S Retail - v1.2.0
MX5100T					
MX5200*					
MX5300XP					
MX5400					
MX5600					
MX5600T					